

T

18 JAN 1965

S E C R E T//CITE NPIC 3625.

COPIES RECEIVED <u>7</u>			
CyNo.	Office	Act.	Rec'd
<u>1</u>	Master File		
<u>2</u>	OS		
	ADMIN		
CENTER	SEC BR		
	P&DS		
	CSD		
	IPD		
	PD		
	PSD		
<u>345</u>	TIO		<u>✓</u>
<u>000</u>	PAG		
	CIA/PID		
CONTINUOUSLY	EX-4		
	SPAD		
ENTLY	NSA LO		
	DIAAP		
ROLLER			
T OF			
	Estimated		

2. ORIGINAL NEGATIVE:

B. 9R SIDE: MINOR STATIC DISCHARGES ARE PRESENT CONTINUOUSLY.

C. SL SIDE: THE OUT BOARD EDGE CONTAINS MINOR STATIC DISCHARGES AND FAINT ROLLER CHATTER TRACES. BOTH TYPES OF DISCHARGES ARE DETECTABLE INTERMITTENTLY ON THE INBOARD EDGE BUT ONLY IN THIN DENSITY AREAS.

D. BOTH SIDES: THE METERING IS EXTREMELY IRREGULAR AND RANGES FROM .050" TO 1.10". IN ADDITION, BOTH SIDES CONTAIN A CONSIDERABLE

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

NUMBER OF OVERLAPPED FRAMES (APPROXIMATELY 5 PERCENT AVERAGE OVERLAP)
AND FRAMES WHICH ARE BUTTED TOGETHER.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OTHER THAN THE
IRREGULAR METERING AND NO PROCESSING ANOMALIES.

3. DUPLICATE POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. THE OVERALL CLOUD COVER IS 5 PERCENT.

S E C R E T

-END OF MESSAGE-

1